

BLACKFEET COMMUNITY WATER PROJECT
BCWP P1-001 - Intake
Stoddard Construction, Contractor

October 9, 2003



Before. Intake project started at this site. Area should look like this again after re-seeding takes next spring.



After. Contractor states the site restoration is complete; their work appears to comply with contract requirements.



Part of the site restoration included establishing drainage control insuring runoff will not flow through control building, PRV vault and well casing. The small stream to the right (not visible in picture) should not overflow site, even at flood stage.



After re-seeding is complete, this area including control building and PRV vault will be fenced. (not part of contract)

Contractor has requested an inspection and issuance of substantial completion. It appears that the work has been completed in accordance with contract requirements. Project engineer will be reviewing the work and meet with contractor on site. That report will be distributed once it has been completed.